Motion - Cable Management O & M Manual


Cleaning Guidelines: Only use non-solvent based cleaner

(1)




Attach top and brottom brackets to cable spine.






Standard orientation: rotate motion links 180° half way through spine length.





Attach top bracket to desk using magnets and/ or screws.





Attach bottom brackets to base using magnets and/or screw.